

US EPA ARCHIVE DOCUMENT

DECONTAMINATION/STAGING SITE ASSESSMENT

Facility Name :	Hopedale Waste Staging	Facility Location ID:	HopW01
Assessment Date :	7/19/2010	Incident Name :	BP Spill
Physical Location :	7222 Hopedale Hwy.		
City, State :	Hopedale, LA	County :	St. Bernard

ASSESSMENT INFORMATION

General Site Information and Observations			
1. All waste stored in lined rolloff boxes?	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input type="checkbox"/> N/A
2. Rolloff boxes covered after filled (or end of day)?	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input type="checkbox"/> N/A
3. Any evidence of oily waste or oily waste waters?	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input type="checkbox"/> N/A
4. If yes, was it adequately addressed?	<input type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> N/A
5. How many samples were collected?			
Additional Comments : Decon Area Containment had failed due to poor maintenance. Richard Mayer brought this to the attention of the Facility Representative Shane Reith. During observation of decon hand boom, containment had failed in one area. Green Algae was noticed indicative of decon water outside of containment approximately 15 feet from the channel. It did not appear to spill into the channel.			